

## ***AGRU COATING***

### Preparation:

New and old surfaces must be free of oil, dirt, fat and loose components.

### Processing:

Stir up thoroughly the content of the vessel. The AGRU COATING can be diluted with water. But do not use too much water, in order to preserve a maximum efficacy. Usually one coating is sufficient, but dependent on the covering also two coatings could be necessary.

The vessel must be closed, because otherwise it is possible that the protective coating will clot. The material mustn't be exposed to temperature below 5°C (41°F).  
- don't let it freeze

Do not process the material at temperatures below 13°C (56°F) resp. above 60°C (140°F).

### Consumption:

approx. 250 g/m<sup>2</sup>

